## 3M General Offices

3M Center St. Paul. Minnesota 55144-1000 (612) 733-1110

Duns No.: 00-617-3082

MATERIAL SAFETY DATA SHEET



MSDS: 3M Super Silicone (White) Part No. 08665 Page 2 MAY 18, 1987 3. FIRE AND EXPLOSION HAZARD DATA FLASH POINT (Closed Cup): >250F FLAMMABLE LIMITS - LEL: N/A EXTINGUISHING MEDIA: CO2, foam, dry chemicals, water SPECIAL FIRE FIGHTING PROCEDURES: Fire fighters should be equipped with self-contained breathing apparatus when fighting fires involving this material. UNUSUAL FIRE AND EXPLOSION HAZARDS: None. 4. REACTIVITY DATA STABILITY: STABLE INCOMPATIBILITY - MATERIALS TO AVOID: Oxidizing materials can cause a reaction. HAZARDOUS POLYMERIZATION: MAY NOT OCCUR HAZARDOUS DECOMPOSITION PRODUCTS: SO2, CO, CO2 and smoke particles when subjected to excessive heat or ------5. ENVIRONMENTAL INFORMATION SPILL RESPONSE: Observe precautions in all sections. Collect spilled material, clean up residue using absorbent material as needed. Place in a U.S. Dept. of Transportation approved metal container and seal. RECOMMENDED DISPOSAL: Material can be disposed by incineration or in a landfill in accordance with local regulations. Dispose of waste/bulk product in a sanitary landfill. Disposal alternative: Incinerate waste/bulk product in an industrial or commercial facility. Consult applicable regulations or authorities before disposal. **ENVIRONMENTAL DATA:** N/D

## 3M General Offices

St. Paul, Minnesota 55144-1000 (612) 733-11.10

Duns No.: 00-617-3082

MATERIAL SAFETY DATA SHEET



MSDS: 3M Super Silicone (White) Part No. 08665 Page 3 MAY 18, 1987 \_\_\_\_\_\_ 6. SUGGESTED FIRST AID EYE CONTACT: Immediately flush eyes with large amounts of water for at least 10 minutes. Call a physician. SKIN CONTACT: Wash affected area with soap and water. INHALATION:

Provide fresh air. IF SWALLOWED:

Call a physician or poison control center. Do not give liquids to an unconscious person.

\_\_\_\_\_ 7. PRECAUTIONARY INFORMATION 

Avoid contact with eyes. Avoid prolonged contact with skin. Avoid breathing vapors during cure; an acid vapor type respiratory is recommended. Keep tightly capped when not in use. Keep out of the reach of children. Use personal protective equipment such as impervious gloves and safety glasses. Provide mechanical or local exhaust ventilation to keep vapor level below the permissable exposure limits.

02-88 2477

## 3M General Offices

3M Center St. Paul. Minnesota 55144-1000 (612) 733-1110

Duns No.: 00-617-3082

MATERIAL SAFETY DATA SHEET



MSDS: 3M Super Silicone (White) Part No. 08665 MAY 18, 1987

Page 4

8. HEALTH HAZARD DATA

## 

EYE CONTACT: May cause irritation upon direct contact. Product releases acetic acid during cure. Contact lens wearers should take appropriate precautions.

SKIN CONTACT: May cause irritation on prolonged contact.

INHALATION: Acetic acid vapors which are released during cure may cause severe irritation to the respiratory system and lung tissue.

INGESTION: May cause digestive system irritation.

The information on this Data Sheet represents our current data and best opinion as to the proper use in handling of this product under normal conditions. Any use of the product which is not in conformance with this Data Sheet or which involves using the product in combination with any other product or any other process is the responsibility of the user.