

MATERIAL SAFETY
DATA SHEET

Copyright, 1999, Minnesota Mining and Manufacturing Company.
All rights reserved. Copying and/or downloading of this information for the purpose of properly utilizing 3M products is allowed provided that:

- 1) the information is copied in full with no changes unless prior agreement is obtained from 3M, and
- 2) neither the copy nor the original is resold or otherwise distributed with the intention of earning a profit thereon.

DIVISION: AUTOMOTIVE AFTERMARKET

TRADE NAME:

3M brand Feathering Disc Adhesive P/N 08041, 08043

ID NUMBER/U.P.C.: 62-1413-2609-0 00-51135-08041-2 62-1413-5509-9 - - -

ISSUED: OCTOBER 26, 1999 (INACTIVE)

SUPERSEDES: AUGUST 29, 1996

DOCUMENT: 10-5937-7

1. INGREDIENT	C.A.S. NO.	PERCENT
HEXANE	110-54-3	15.0 - 40.0
OTHER HEXANE ISOMERS	Unknown	10.0 - 30.0
HYDROCARBON RESIN	73905-20-1	10.0 - 30.0
STYRENE-BUTADIENE POLYMER	9003-55-8	10.0 - 30.0
GLYCEROL ESTERS OF ROSIN ACIDS	8050-31-5	5.0 - 10.0

THIS PRODUCT CONTAINS THE FOLLOWING TOXIC CHEMICAL OR CHEMICALS SUBJECT TO THE REPORTING REQUIREMENTS OF SECTION 313 OF TITLE III OF THE EMERGENCY PLANNING AND COMMUNITY RIGHT-TO-KNOW ACT OF 1986 AND 40 CFR PART 372:

HEXANE

2. PHYSICAL DATA

BOILING POINT:..... 148F Hexane
 VAPOR PRESSURE:..... 126.5 mm @ 68F
 VAPOR DENSITY:..... 2.97
 EVAPORATION RATE:..... 1.9
 SOLUBILITY IN WATER:..... Very slight
 SP. GRAVITY:..... 0.78
 PERCENT VOLATILE:..... 60.00 % by wt
 pH:..... N/A
 VISCOSITY:..... 2,560 Centistokes
 MELTING POINT..... N/D
 APPEARANCE AND ODOR: low viscosity liquid, translucent, strong hexane odor

3. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT:..... -10F
 FLAMMABLE LIMITS - LEL:..... 1.2
 FLAMMABLE LIMITS - UEL:..... 6.9
 AUTOIGNITION TEMPERATURE: ... N/D
 EXTINGUISHING MEDIA:
 Carbon dioxide, Dry chemical, Foam
 SPECIAL FIRE FIGHTING PROCEDURES:
 Wear full protective clothing, including helmet, self-contained,

Abbreviations: N/D - Not Determined N/A - Not Applicable CA - Approximately

MATERIAL SAFETY
DATA SHEETMSDS: 3M brand Feathering Disc Adhesive P/N 08041, 08043
OCTOBER 26, 1999

PAGE: 2 of 5

3. FIRE AND EXPLOSION HAZARD DATA (continued)

positive pressure or pressure demand breathing apparatus, bunker coat and pants, bands around arms, waist and legs, face mask, and protective covering for exposed areas of the head.

UNUSUAL FIRE AND EXPLOSION HAZARDS:

Closed containers exposed to heat from fire may build pressure and explode. Vapors may travel long distances along the ground or floor to an ignition source and flash back.

NFPA HAZARD CODES: HEALTH: 2 FIRE: 3 REACTIVITY: 0
UNUSUAL REACTION HAZARD: none

4. REACTIVITY DATA

STABILITY: Stable**INCOMPATIBILITY - MATERIALS TO AVOID:**

Not applicable.

HAZARDOUS POLYMERIZATION: Will Not Occur**HAZARDOUS DECOMPOSITION PRODUCTS:**

Carbon Monoxide and Carbon Dioxide, Toxic Vapors, Gases or Particulates.

5. ENVIRONMENTAL INFORMATION

SPILL RESPONSE:

Refer to other sections of this MSDS for information regarding physical and health hazards, respiratory protection, ventilation, and personal protective equipment. Extinguish all ignition sources. Cover with inorganic absorbent material. Collect using non-sparking tools. Place in a U.S. DOT-approved container.

RECOMMENDED DISPOSAL:

Incinerate in a permitted hazardous waste incinerator in the presence of a combustible material. Dispose of waste product in a facility permitted to accept chemical waste.

ENVIRONMENTAL DATA:

Not determined.

REGULATORY INFORMATION:

Volatile Organic Compounds: 468 gms/liter South Coast Air Quality

Mgmt Dist Method Rule 443.1, calculated.

VOC Less H₂O & Exempt Solvents: 468 gms/liter South Coast Air Quality

Mgmt Dist Method Rule 443.1, calculated.

Since regulations vary, consult applicable regulations or authorities before disposal. U.S. EPA Hazardous Waste Number = D001 (Ignitable)

EPCRA HAZARD CLASS:**FIRE HAZARD: Yes PRESSURE: No REACTIVITY: No ACUTE: Yes CHRONIC: Yes**

MATERIAL SAFETY
DATA SHEET

MSDS: 3M brand Feathering Disc Adhesive P/N 08041, 08043
OCTOBER 26, 1999

PAGE: 3 of 5

6. SUGGESTED FIRST AID

EYE CONTACT:

Immediately flush eyes with large amounts of water. Get immediate medical attention.

SKIN CONTACT:

Flush skin with large amounts of water. If irritation persists, get medical attention.

INHALATION:

Remove person to fresh air. If not breathing, give artificial respiration. If breathing is difficult, get immediate medical attention.

IF SWALLOWED:

If swallowed, call a physician immediately. Only induce vomiting at the instruction of a physician. Never give anything by mouth to an unconscious person.

7. PRECAUTIONARY INFORMATION

EYE PROTECTION:

Avoid eye contact. Wear vented goggles. Wear safety glasses with side shields.

SKIN PROTECTION:

Avoid skin contact. Wear appropriate gloves when handling this material. A pair of gloves made from the following material(s) are recommended: nitrile rubber, polyethylene/ethylene vinyl alcohol, polyvinyl alcohol, polytetrafluoroethylene (Teflon), fluoroelastomer (Viton).

VENTILATION PROTECTION:

Use in a well-ventilated area. Provide sufficient ventilation to maintain emissions below recommended exposure limits.

RESPIRATORY PROTECTION:

Avoid prolonged breathing of vapors.

PREVENTION OF ACCIDENTAL INGESTION:

Do not ingest.

RECOMMENDED STORAGE:

Keep container closed when not in use. Keep out of the reach of children.

FIRE AND EXPLOSION AVOIDANCE:

Keep container tightly closed. Keep away from heat, sparks, open flame, and other sources of ignition. Extremely flammable liquid and vapor.

MATERIAL SAFETY
 DATA SHEET



MSDS: 3M brand Feathering Disc Adhesive P/N 08041, 08043
 OCTOBER 26, 1999

PAGE: 4 of 5

7. PRECAUTIONARY INFORMATION (CONTINUED)

INGREDIENTS	EXPOSURE LIMITS		TYPE	AUTH	SKIN*
	VALUE	UNIT			
HEXANE	50	ppm	TWA	ACGIH	Y
HEXANE	50	ppm	TWA	OSHA	
OTHER HEXANE ISOMERS	NONE	NONE	NONE	NONE	
HYDROCARBON RESIN	NONE	NONE	NONE	NONE	
STYRENE-BUTADIENE POLYMER	NONE	NONE	NONE	NONE	
GLYCEROL ESTERS OF ROSIN ACIDS	NONE	NONE	NONE	NONE	

* SKIN NOTATION: Listed substances indicated with "Y" under SKIN refer to the potential contribution to the overall exposure by the cutaneous route including mucous membrane and eye, either by airborne or, more particularly, by direct contact with the substance. Vehicles can alter skin absorption.

SOURCE OF EXPOSURE LIMIT DATA:

- ACGIH: American Conference of Governmental Industrial Hygienists
- AIHA: American Industrial Hygiene Assoc. Workplace Environmental Exposure Level G
- OSHA: Occupational Safety and Health Administration
- NONE: None Established

8. HEALTH HAZARD DATA

EYE CONTACT:

Moderate Eye Irritation: signs/symptoms can include redness, swelling, pain, tearing, and hazy vision.

SKIN CONTACT:

Mild Skin Irritation (after prolonged or repeated contact): signs/symptoms can include redness, swelling, and itching.

May be absorbed through the skin in harmful amounts.

INHALATION:

Central Nervous System Depression: signs/symptoms can include headache, dizziness, drowsiness, incoordination, slowed reaction time, slurred speech, giddiness and unconsciousness.

Irritation (upper respiratory): signs/symptoms can include soreness of the nose and throat, coughing and sneezing.

WHILE THE FOLLOWING EFFECTS ARE ASSOCIATED WITH ONE OR MORE OF THE INDIVIDUAL INGREDIENTS IN THIS PRODUCT AND ARE REQUIRED TO BE INCLUDED ON THE MSDS BY THE U.S. OSHA HAZARD COMMUNICATION STANDARD, THEY ARE NOT EXPECTED EFFECTS DURING FORESEEABLE USE OF THIS PRODUCT.

Peripheral Neuropathy: signs/symptoms can include tingling of extremities, incoordination, numbness, weakness and tremors.

IF SWALLOWED:

Ingestion may cause:

MATERIAL SAFETY
DATA SHEETMSDS: 3M brand Feathering Disc Adhesive P/N 08041, 08043
OCTOBER 26, 1999

PAGE: 5 of 5

8. HEALTH HAZARD DATA (continued)

Irritation of Gastrointestinal Tissues: signs/symptoms can include pain, vomiting, abdominal tenderness, nausea, blood in vomitus, and blood in feces.

WHILE THE FOLLOWING EFFECTS ARE ASSOCIATED WITH ONE OR MORE OF THE INDIVIDUAL INGREDIENTS IN THIS PRODUCT AND ARE REQUIRED TO BE INCLUDED ON THE MSDS BY THE U.S. OSHA HAZARD COMMUNICATION STANDARD, THEY ARE NOT EXPECTED EFFECTS DURING FORESEEABLE USE OF THIS PRODUCT.

Central Nervous System Depression: signs/symptoms can include headache, dizziness, drowsiness, muscular weakness, incoordination, slowed reaction time, fatigue, blurred vision, slurred speech, giddiness, tremors and convulsions.

Aspiration Pneumonitis: signs/symptoms can include coughing, difficulty breathing, wheezing, coughing up blood and pneumonia, which can be fatal.

SECTION CHANGE DATES

INGREDIENTS	SECTION CHANGED SINCE AUGUST 29, 1996 ISSUE
-------------	---

Abbreviations: N/D - Not Determined N/A - Not Applicable CA - Approximately

The information in this Material Safety Data Sheet (MSDS) is believed to be correct as of the date issued. 3M MAKES NO WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR COURSE OF PERFORMANCE OR USAGE OF TRADE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's method of use or application. Given the variety of factors that can affect the use and application of a 3M product, some of which are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for user's method of use or application.

3M provides information in electronic form as a service to its customers. Due to the remote possibility that electronic transfer may have resulted in errors, omissions or alterations in this information, 3M makes no representations as to its completeness or accuracy. In addition, information obtained from a database may not be as current as the information in the MSDS available directly from 3M.